



Photograph 1. View of cooling pond berm looking southwest showing wood cribbing within the berm.



Photograph 2. Close up view of wood cribbing in cooling pond berm.





Photograph 3. View of wood cribbing in berm near the west end of the cooling pond.



Photograph 4. Remnants of a wood retaining wall along a portion of the southern perimeter of the cooling pond.





Photograph 5. View of the cooling pond berm looking east from the west end.



Photograph 6. View of the cooling pond showing the low water level. Note the outlet culvert in the northeast (upper left) corner of the pond.





Photograph 7. Seep area on the berm near the west end of the cooling pond looking south. The seep discharges under the logs into the Blackfoot River.



Photograph 8. View of drill rig and barge on the cooling pond.





Photograph 9. View of the cooling pond berm looking west with the cooling pond on the south (left) and the Blackfoot River on the north (right).



Photograph 10. Sonic drill rig at soil boring B-13 on the west end of the cooling pond berm.





Photograph 11. Log yard waste piles east of the cooling pond.



Photograph 12. Sunken log debris in the Blackfoot River.





Photograph 13. Log debris in the Blackfoot River at the toe of the cooling pond berm looking west.



Photograph 14. Riprap, alluvium, logs and soil fill observed on the east end of the cooling pond berm.





Photograph 15. Concrete debris on the edge of the cooling pond berm. Note the wood cribbing in the background.



Photograph 16. Concrete debris (lower right) in the Blackfoot River at the edge of the berm. Note the wood cribbing (upper right) and wood debris (background).